



**CHILDREN'S EDUCATION SOCIETY (Regd.)**  
**THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.

Approved by A.I.C.T.E. New Delhi.

Recognised by UGC Under Section 2(f)

Bommanahalli, Hosur Road, Bangalore - 560 068.

Ph: 080-61754601/602, Fax: 080 - 25730551

E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

**INDEX**

Sl. No.	Particulars	Page No.
1.	Solar Panel installation bill	1-2
2.	BESCOM Bill	3
3.	Maintenance Bill	4-8
4.	Technical Feasibility Report by Bangalore Electricity Supply Company Limited	9

  
**PRINCIPAL**  
The Oxford College of Engineering  
Bommanahalli, Hosur Road  
Bengaluru-560 068



**CHILDREN'S EDUCATION SOCIETY (Regd.)**  
**THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.  
Approved by A.I.C.T.E. New Delhi.  
Recognised by UGC Under Section 2(f)  
Bommanahalli, Hosur Road, Bangalore - 560 068.  
Ph: 080-61754601/602, Fax: 080 - 25730551  
E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

### Solar Bills

Cell-9845747572  
9008401372

**SHIVAM TRADERS**  
Akshaya Nagar Main Road, Yalenahalli Bus Stop opp. Fullinfaas College, Bangalore-560068.  
E-Mail ID: kisanaiqal@gmail.com

DATE: 09-12-2021

The Oxford Education Institution  
Bommanahalli  
Bangalore-560068

**BILL**  
New Boy's Hostel

Sl no	Particulars	Quantity	Rate Rs.	Amount Rs.
1	Solar Panel Drilling & Copper Braising Services & Re Insulation	96 panels	1,600.00	1,53,600.00
2	New solar tank stainless steel, 2mm thickness 304 gauges	2500 ltr 2 nos	1,75,000/-	3,50,000/-
3	Loss = Old solar tank replacement (Rackold)	2500 ltr 2 nos	20,000/-	40,000/-
<b>Total Amount</b>				4,63,600/-
<b>Advance Amount</b>				2,30,000/-
<b>Balance Amount</b>				2,33,000/-

Note: 1 Year Warranty.  
Total: (Two lakhs thirty three thousand Only)

*Work is completed  
Kindly release the  
payment*  
10/12/21  
General Boy's Hostel Warden  
10/12/21

*Remarks: Hot water distribution is finish and from yesterday 09/12/21 getting hot water*

For SHIVAM TRADERS  
Authorized Signature  
Balance: 2,33,000/-  
10/12/21

**GPS Map  
Camera Lite**

23, AMR Tech Park Internal Rd, Hongasandra,  
Bengaluru, Karnataka 560068, India

Latitude  
12.9007416°

Longitude  
77.6320971°

Local 01:14:04 PM  
GMT 07:44:04 AM

Altitude 810.7 meters  
Friday, 31-12-2021



**CHILDREN'S EDUCATION SOCIETY (Regd.)**  
**THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.  
Approved by A.I.C.T.E. New Delhi.

Recognised by UGC Under Section 2(f)  
Bommanahalli, Hosur Road, Bangalore - 560 068.  
Ph: 080-61754601/602, Fax: 080 - 25730551

E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

*To chairman Sir.  
Advance of 2.30 lacs may pls.  
be approved to commence the work.*

NEW GENERAL HOSTEL  
10<sup>th</sup> mile stone, Hosur Road, Bommanahalli, Bangalore - 560 068.

Dated: 27.11.2019

M/s Shyam Traders  
Akshaya Nagar Main Road,  
Yelenahalli Bus Stop Opp Fullinfaws college,  
Bangalore 68.

Dear Sir,

Sub: Work Order for Rectification of Solar water Heating works

With reference to the above subject, your Quotation No. dated 11.08.2019 and further discussions held with undersigned, we are glad to place our Work Order on you for work as above & details shown below:

Sl.No	Particulars	Qty	Rate	Amount
01	Solar Panel Drilling & Copper Braising services & Ro Insulation	96	1,600	1,53,600
02	New solar tank stainless steel, 2.5mm thickness 304 guages	2500ltr 2nos	1,75,000	3,50,000
03	Less =old solar tank replacement(Rackold)	2500ltr 2nos	20,000	40,000
				4,63,000

**TERMS AND CONDITIONS:**

Price : Total Order Value Rs.4,63,000/- (Rupees Four Lakhs Sixty Three Thousand Only)  
All Inclusive.

Delivery : The above items to be delivered, Installed & commissioned within 10 days at New General Hostel 10th mile stone, Hosur Road, Bommanahalli, Bangalore -68.  
Contact Person: Raviraju 9886109811

Payment : 50% Advance enclosed along with work order. After completion of work & necessary certification.

Warranty : 1 year against any manufacturing defects.

Billing : Your invoice should be in New General Hostel 10th mile stone, Hosur Road Bommanahalli, Bangalore -68. Billing at Actuals.

Please confirm acceptance of order.

Thanking you,

*Advance 22,30,000/- By cheque  
10/12/19*

Yours faithfully,

**GPS Map  
Camera Lite**

23, AMR Tech Park Internal Rd, Hongasandra,  
Bengaluru, Karnataka 560068, India

Latitude  
12.9003404°

Longitude  
77.6331748°

Local 01:13:52 PM  
GMT 07:43:52 AM

Altitude 0 meters  
Friday, 31-12-2021

2

*[Signature]*  
**PRINCIPAL**  
The Oxford College of Engineering  
Bommanahalli, Hosur Road  
Bangalore-560 068



**CHILDREN'S EDUCATION SOCIETY (Regd.)**  
**THE OXFORD COLLEGE OF ENGINEERING**  
 (Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.  
 Approved by A.I.C.T.E. New Delhi.  
 Recognised by UGC Under Section 2(f)  
 Bommanahalli, Hosur Road, Bangalore - 560 068.  
 Ph: 080-61754601/602, Fax: 080 - 25730551  
 E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

**BESCOM BILL**

AMPLUS SOLAR BILLS

**The Oxford Group of Institutions**  
**Department - Electrical and Electronics Engineering-Salar and BESCOM Bill**

Sl. No.	Month/Year	BESCOM Consumption in kWh	Power consumed by both in kWh	Total power consumed by both in kWh	Amount paid to be Paid in Rs	Actual BESCOM Bill in Rs	Amount paid in Rs	Balance (over/short) in Rs	Total (BESCOM+Solar) in Rs	Tax Paid in Rs	Invoice No.	Invoice Date	Due Date	
1	Feb-19	42855	21164	64019	48246.1	184131.4	106075	276386.5	402156.4	4561	ASPP/181800607	6-Mar-2019	13-Mar-2019	
2	Mar-19	58428	30254	88682	65266.5	312704	152781	465423	274477	81270	ASPP/182000101	8-Apr-2019	15-Apr-2019	
3	Apr-19	61875	29314	91189	71308.5	430377	145192	575569	310584.5	80554	ASPP/182000103	1-May-2019	8-May-2019	
4	May-19	79774	39211	118985	89551.5	663000	182484	845485.5	207688	64888	ASPP/182000104	2-Jun-2019	9-Jun-2019	
5	Jun-19	41221	21841	63062	46675.7	463887	124811	588700	82346	26244	ASPP/182000107	2-Jul-2019	9-Jul-2019	
6	Jul-19	49620	23116	72736	53609.9	466630	110734	577265	483824	6260	ASPP/182000112	2-Aug-2019	9-Aug-2019	
7	Aug-19	49209	25258	74467	53787.2	464119	109770	573889	503010	6075	ASPP/182000117	2-Sep-2019	9-Sep-2019	
8	Sep-19	43224	21461	64685	46403.4	464116	113450	528132	465410	60116	ASPP/182000121	2-Oct-2019	9-Oct-2019	
9	Oct-19	48280	23524	71804	53202.6	430180	122084	552264	481509.4	62801	ASPP/182000124	2-Nov-2019	9-Nov-2019	
10	Nov-19	45334	24874	70208	46152.5	464116	113450	528132	465410	60116	ASPP/182000128	2-Dec-2019	9-Dec-2019	
11	Dec-19	44678	21181	65859	45602.2	430180	122084	552264	481509.4	62801	ASPP/182000134	2-Jan-2020	9-Jan-2020	
12	Jan-20	45100	22754	67854	45175.5	430180	122084	552264	481509.4	62801	ASPP/182000137	2-Feb-2020	9-Feb-2020	
13	Feb-20	41525	21491	63016	44327.2	324908.2	138417	462326.4	423966.4	21307	ASPP/192001002	2-Mar-2020	9-Mar-2020	
14	Mar-20	41300	20174	61474	44793.6	262582.5	152129	419712.1	331482	ASPP/201000017	1-Apr-2020	8-Apr-2020		
15	Apr-20	14739	7124	21863	15979.7	28145	149379	149379	149379	178024	ASPP/201000155	1-May-2020	8-May-2020	
16	May-20	19130	26590	45720	34922.5	77126.25	133825	210951.25	138721	ASPP/201000180	1-Jun-2020	8-Jun-2020		
17	Jun-20	20350	27061	47411	32485.45	123245	111418	234663	89796	ASPP/201000382	1-Jul-2020	8-Jul-2020		
18	Jul-20	19425	21167	40592	31205.8	105582	107903	213485	68574	ASPP/201000518	1-Aug-2020	8-Aug-2020		
19	Aug-20	24625	20753	45378	34714.7	104457.5	104407	104407	104407	282268.5	27481	ASPP/201000699	2-Sep-2020	9-Sep-2020
20	Sep-20	28725	29242	57967	38960.5	30025.74	103222	308430.75	77480	ASPP/201000779	2-Oct-2020	9-Oct-2020		
21	Oct-20	27900	23603	51503	40428.55	130746.25	131935	131995	399941.25	104357	ASPP/201000910	2-Nov-2020	9-Nov-2020	
22	Nov-20	30023	22492	52515	41228.45	209790	13555	333775	88893	ASPP/201001056	2-Dec-2020	9-Dec-2020		
23	Dec-20	55480	23811	79291	46574.35	265477.5	120590	386067.5	79672	ASPP/201010115	2-Jan-2021	9-Jan-2021		
24	Jan-21	34624	24630	59254	465151.75	232720	124387	327102	88950	ASPP/201010178	2-Feb-2021	9-Feb-2021		
25	Feb-21	29125	28106	57231	449263.35	211410	141935	353345	25918	ASPP/201011523	2-Mar-2021	9-Mar-2021		
26	Mar-21	47590	31724	79314	623759.4	360157.5	160257	520414.8	92965	ASPP/212200056	03-Apr-2021	10-Apr-2021		
27	Apr-21	42375	21681	64056	524239.6	330355	136689	467044	84196	ASPP/212200226	2-May-2021	9-May-2021		
28	May-21	18675	26653	45328	355824.8	51840	134598	186498	169387	ASPP/212200184	2-Jun-2021	9-Jun-2021		
29	Jun-21	15278	22792	40770	320009.2	83035	115125	198160	111910	ASPP/212200571	1-Jul-2021	10-Jul-2021		
30	Jul-21	32025	20122	52147	427605.4	242928	101616	344541	33064	ASPP/212200689	1-Aug-2021	8-Aug-2021		
31	Aug-21	41275	21630	62905	515821	324925	109222	109222	434157	81664	ASPP/212200648	1-Sept-2021	8-Sept-2021	
32	Sep-2021	40120	22148	62268	510638.6	315085	111847	426932	33707	ASPP/212201010	2-Oct-2021	9-Oct-2021		
33	Oct-2021	44736	19153	63889	519249.6	349478	86723	444199	75092	ASPP/212201173	1-Nov-2021	8-Nov-2021		
34	Nov-2021	45723	14329	60054	492442.8	347860	22381	470241	439721	57722	ASPP/212201339	1-Dec-2021	8-Dec-2021	
<b>Total</b>		<b>1374839</b>	<b>812497</b>	<b>2187336</b>	<b>1801855.2</b>	<b>10043877</b>	<b>4163612</b>	<b>6136528</b>	<b>14197483</b>	<b>2899019</b>				

Part payment paid on 14.11.2011 208570

Remaining balance to be paid Rs 72361

Seventy two thousand three hundred and sixty one only

Forwarded to chairman & Co. for approval

*Principal* 23/12/21



**CHILDREN'S EDUCATION SOCIETY (Regd.)  
THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.

Approved by A.I.C.T.E. New Delhi.


Recognised by UGC Under Section 2(f)

Bommanahalli, Hosur Road, Bangalore - 560 068.

Ph: 080-61754601/602, Fax: 080 - 25730551

E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

**MAINTENANCE BILL**




**THE OXFORD COLLEGE OF ENGINEERING**  
15th Block, Bommanahalli, Hosur Road - 560 068  
Approved by A.I.C.T.E. New Delhi, recognised by N.M.T. New Delhi & Affiliated to VTU, Belagavi


**LOG BOOK REGARDING MAINTENANCE WORKS**      Year: 2017

Type of Maintenance Work: Computer work, log sheets


Sl.No	Date	Building/Floor/Room	Nature of Work	Repaired/ Serviced by	Date of Repaired/ Serviced	Signature of the Technician	Signature of the Supervisor
1	29/6/17	MCA 617	Window checked & WP	KUMAR	29/6/17	<i>Kumar</i>	<i>P</i>
2	17/7/17	AU-Lab 303	Furniture repair	KUMAR	17/7/17	<i>Kumar</i>	<i>P</i>
3	19/7/17	IS-T Seminar hall	Fixing of window & window cleaning	KUMAR	19/7/17	<i>Kumar</i>	<i>P</i>
4	25/7/17	ISEN 422	Window checked	KUMAR	25/7/17	<i>Kumar</i>	<i>P</i>
5	28/7/17	ECE PC Lab 311	Window checked & WP	KUMAR	28/7/17	<i>Kumar</i>	<i>P</i>
6	5/8/17	CV- 2005	Window checked & WP	KUMAR	5/8/17	<i>Kumar</i>	<i>P</i>
7	10/8/17	MBA Seminar center 206	Chair check	KUMAR	10/8/17	<i>Kumar</i>	<i>P</i>
8	22/8/17	ISE Seminar 2105	Furniture & window check	KUMAR	22/8/17	<i>Kumar</i>	<i>P</i>
9	29/8/17	AU 607	Desk lock replaced	KUMAR	29/8/17	<i>Kumar</i>	<i>P</i>
10	8/9/17	CV HOD room 2114	Chair, table & desk	KUMAR	8/9/17	<i>Kumar</i>	<i>P</i>
11	8/8/17	AU 607	Desk lock replaced	KUMAR	8/8/17	<i>Kumar</i>	<i>P</i>
12	8/9/17	CV HOD room 2114	Chair & table supply	KUMAR	8/9/17	<i>Kumar</i>	<i>P</i>


Maintenance Committee Co-Ordinator: *[Signature]*      Head - Maintenance Committee: *[Signature]*  
The Oxford College of Engineering, Bangalore-560 068





**Bengaluru, Karnataka, India**  
23, AMR Tech Park Internal Rd, Hongasandra, Bengaluru, Karnataka  
560068, India  
Lat 12.901002°  
Long 77.631072°  
31/12/21 03:18 PM

  
**PRINCIPAL**  
 4 The Oxford College of Engineering  
 Bommanahalli, Hosur Road  
 Bengaluru-560 068



**CHILDREN'S EDUCATION SOCIETY (Regd.)  
THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.

Approved by A.I.C.T.E. New Delhi.

Recognised by UGC Under Section 2(f)

Bommanahalli, Hosur Road, Bangalore - 560 068.

Ph: 080-61754601/602, Fax: 080 - 25730551

E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

**THE OXFORD COLLEGE OF ENGINEERING**

1st Floor Block, Bommanahalli, Bangalore - 560 068  
23/Amr Tech Park Internal Rd, Hosur Road, Bangalore - 560 068  
(Approved by AICTE, New Delhi, Accredited by NBA, New Delhi & Affiliated to VTU, Belagavi)

**LOG BOOK REGARDING MAINTENANCE WORKS**

Year: 2018


Type of Maintenance Work: carpenter work, log sheet.

Sl.No	Date	Building/Floor /Room	Nature or Work	Repaired/ Serviced by	Date of Repaired/ Serviced	Signature of the Technician	Signature of the Supervisor
1	6/3/18	Physics 102	Door locks replaced	Kumar	6/3/18	<i>Kumar</i>	<i>[Signature]</i>
2	12/03/18	Bio-Technology Seminar hall 303	Furniture, window screen checking	Kumar	12/03/18	<i>Kumar</i>	<i>[Signature]</i>
3	22/03/18	MCA-614	Classroom door, window screen checking	Kumar	22/03/18	<i>Kumar</i>	<i>[Signature]</i>
4	27/03/18	ECE-labos	Door locks replaced	Kumar	27/03/18	<i>Kumar</i>	<i>[Signature]</i>
5	06/04/18	MBA-602	Furniture repair	Kumar	06/04/18	<i>Kumar</i>	<i>[Signature]</i>
6	11/04/18	AV 607	Door checking repair	Kumar	11/04/18	<i>Kumar</i>	<i>[Signature]</i>
7	21/04/18	MCA-lab/601	Furniture repair	Kumar	21/04/18	<i>Kumar</i>	<i>[Signature]</i>
8	25/04/18	MBA-601	Chair checking repair	Kumar	25/04/18	<i>Kumar</i>	<i>[Signature]</i>
9	04/05/18	ISE-N422	Door locks replaced	Kumar	4/5/18	<i>Kumar</i>	<i>[Signature]</i>
10	10/05/18	AV-Seminar hall 601	Furniture window screen checking	Kumar	10/5/18	<i>Kumar</i>	<i>[Signature]</i>
11	10/05/18	AV-Seminar hall 601	Furniture window screen checking	Kumar	10/5/18	<i>Kumar</i>	<i>[Signature]</i>
12	10/05/18	AV-Seminar hall 601	Furniture window screen checking	Kumar	10/5/18	<i>Kumar</i>	<i>[Signature]</i>

Maintenance Committee Co-Ordinator

*[Handwritten Signature]*

Head of the Department  
Head of the Department of Civil Engineering  
The Oxford College of Engineering  
Bangalore - 560 068



**Bengaluru, Karnataka, India**

23, AMR Tech Park Internal Rd, Hongasandra, Bengaluru, Karnataka  
560068, India

Lat 12.901006°

Long 77.631057°

31/12/21 03:19 PM

**PRINCIPAL**

The Oxford College of Engineering  
Bommanahalli, Hosur Road  
Bengaluru-560 068





**CHILDREN'S EDUCATION SOCIETY (Regd.)  
THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.

Approved by A.I.C.T.E. New Delhi.

Recognised by UGC Under Section 2(f)

Bommanahalli, Hosur Road, Bangalore - 560 068.

Ph: 080-61754601/602, Fax: 080 - 25730551

E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

**THE OXFORD COLLEGE OF ENGINEERING**

Hosur Road, Bommanahalli, Bangalore-560 068  
21/1 Hosur Road, Bommanahalli, Bangalore-560 068  
Approved by AICTE, New Delhi, Accredited by NBA, New Delhi & Affiliated to VTU, Belagavi

**LOG BOOK REGARDING MAINTENANCE WORKS**


Year: 2020

Type of Maintenance Work: corporate work log sheet

Sl.No	Date	Building/Floor /Room	Nature of Work	Repaired/ Serviced by	Date of Repaired/ Serviced	Signature of the Technician	Signature of the Supervisor
1	3/11/20	AV - 607	chairs and bench repaired	Kumar	3/11/20	<i>Kumar</i>	<i>[Signature]</i>
2	12/11/20	chemistry lab-1	furniture repaired	Kumar	12/11/20	<i>Kumar</i>	<i>[Signature]</i>
3	19/11/20	Maths- 801	chairs and benches repaired	Kumar	19/11/20	<i>Kumar</i>	<i>[Signature]</i>
4	26/11/20	MBA - 703	chairs repaired and checking	Kumar	26/11/20	<i>Kumar</i>	<i>[Signature]</i>
5	5/12/20	ISE - N422	chairs and benches repair	Kumar	5/12/20	<i>Kumar</i>	<i>[Signature]</i>
6	8/12/20	Mechatronics 804	chairs and benches repair	Kumar	8/12/20	<i>Kumar</i>	<i>[Signature]</i>
7	11/12/20	EEE - 505	chairs and benches repair	Kumar	11/12/20	<i>Kumar</i>	<i>[Signature]</i>
8	12/12/20	physics - 105	chairs and benches repair	Kumar	12/12/20	<i>Kumar</i>	<i>[Signature]</i>
9	23/12/20	CSE - N312	chairs and benches repair	Kumar	23/12/20	<i>Kumar</i>	<i>[Signature]</i>
10	29/12/20	ECE - 402	chairs and benches repair	Kumar	29/12/20	<i>Kumar</i>	<i>[Signature]</i>
11	29/12/20	ECE - 402	chairs and benches repair	Kumar	29/12/20	<i>Kumar</i>	<i>[Signature]</i>
12	29/12/20	ECE - 402	chairs and benches repair	Kumar	29/12/20	<i>Kumar</i>	<i>[Signature]</i>

Maintenance Committee Co-Ordinator

Professor, Head EEE  
Head, Maintenance Committee Engg.  
The Oxford College of Engineering  
Bommanahalli, Hosur Road  
Bangalore - 560 068



**Bengaluru, Karnataka, India**

1st & 2nd Floor, IBIS Hotel, 21/1 Hosur Road, Bommanahalli, AMR Tech Park Internal Rd, Hongasandra, Bengaluru, Karnataka 560068, India

Lat 12.901012°

Long 77.631374°

31/12/21 03:20 PM

**PRINCIPAL**  
The Oxford College of Engineering  
Bommanahalli, Hosur Road  
Bengaluru-560 068





**CHILDREN'S EDUCATION SOCIETY (Regd.)**  
**THE OXFORD COLLEGE OF ENGINEERING**  
 (Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.  
 Approved by A.I.C.T.E. New Delhi.  
 Recognised by UGC Under Section 2(f)  
 Bommanahalli, Hosur Road, Bangalore - 560 068.  
 Ph: 080-61754601/602, Fax: 080 - 257 30551  
 E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org



**THE OXFORD COLLEGE OF ENGINEERING**  
Hosur Road, Bommanahalli, Bangalore-560 068  
 25WebSite: www.theoxford.edu Email: engprincipal@theoxford.edu  
 (Approved by AICTE, New Delhi, Accredited by NBA, New Delhi & Affiliated to VTU, Belgaum)

**LOG BOOK REGARDING MAINTENANCE WORKS** Year: 2020 - 2021

Type of Maintenance Work: Sewage Treatment Plant (STP) maintenance

Sl.No	Date	Building/Floor /Room	Nature or Work	Repaired/ Serviced by	Date of Repaired/ Serviced	Signature of the Technician	Signature of the Supervisor
1	29/08/2020	STP	Down stream equipment failure	Kiran Kumar	29/08/20	Kar	[Signature]
2	20/09/2020	STP	Filtration problem	Kaling Kumar	20/09/20	Kar	[Signature]
3	19/10/2020	STP	Down stream equipment	Kaling Kumar	19/10/20	Kar	[Signature]
4	26/11/2020	STP	Blockage	Kiran Kumar	26/11/20	Kar	[Signature]
5	31/12/2020	STP	Disposal of excess sludge	Kaling Kumar	31/12/20	Kar	[Signature]
6	12/01/2021	STP	Downstream equipment failure	Kaling Kumar	12/01/21	Kar	[Signature]
7	14/02/2021	STP	Filtration problem	Kaling Kumar	14/02/21	Kar	[Signature]
8	12/03/2021	STP	Pumping problem	Kiran Kumar	12/03/21	Kar	[Signature]
9	14/03/2021	STP	Pumping problem	Kiran Kumar	14/03/21	Kar	[Signature]
10	17/03/2021	STP	Pumping problem	Kiran Kumar	17/03/21	Kar	[Signature]
11	17/03/2021	STP	Pumping problem	Kiran Kumar	17/03/21	Kar	[Signature]
12	17/03/2021	STP	Pumping problem	Kiran Kumar	17/03/21	Kar	[Signature]

Maintenance Committee Co-ordinator Head Maintenance Committee  
The Oxford College of Engineering  
 Bommanahalli, Hosur Road  
 Bangalore-560 068

**Bengaluru, Karnataka, India**  
 23, AMR Tech Park Internal Rd, Hongasandra, Bengaluru, Karnataka  
 560068, India  
 Lat 12.900977°  
 Long 77.631088°  
 31/12/21 02:49 PM

Google C Bank

GPS Map Camera

**PRINCIPAL**  
 The Oxford College of Engineering  
 Bommanahalli, Hosur Road  
 Bengaluru-560 068



**CHILDREN'S EDUCATION SOCIETY (Regd.)  
THE OXFORD COLLEGE OF ENGINEERING**

(Recognised by the Govt. of Karnataka, Affiliated to Visvesvaraya Technological University, Belagavi.  
Approved by A.I.C.T.E. New Delhi.  
Recognised by UGC Under Section 2(f)  
Bommanahalli, Hosur Road, Bangalore - 560 068.  
Ph: 080-61754601/602, Fax: 080 - 25730551  
E-mail: engprincipal@theoxford.edu Web: www.theoxfordengg.org

**BANGALORE ELECTRICITY SUPPLY COMPANY LIMITED**  
(Wholly owned by Government of Karnataka Undertaking)  
**Technical Feasibility Report**  
(To be submitted by the Section officer)

Sl No.	Parameter	Utility Observation
<b>A Distribution Transformer Details</b>		
1	Location	
2	Capacity in KVA	OXFORD Egg College
3	Total Connected load in kW	750 KVA
5	SRTPV already Proposed/connected in kWp	108 kW 417 kW
6	Proposed SRTPV capacity in kWp	
7	Total Generation Capacity (5+6) in kWp	202 kWp
8	Whether the transformer capacity is adequate to deliver the proposed SRTPV system in addition to existing solar RTPV systems* (The Transformer shall be loaded upto 80% of capacity)	Yes/No EXISTING HT INSTALLATION CD, 400 KVA
<b>B Feeder Details</b>		
9	Name of the 11kV Feeder	HSR MUSS
10	Capacity of the 11kV Sub Station	F 14 HSR
11	Name of the 11kV Sub Station	F 14
12	Name of the 11kV Sub Station	66/11 KVA HSR MUSS
13	Name of the 11kV Sub Station	400 sq mm XLPE UG cable
14	Total capacity (kWp) of SRTPV systems connected on the feeder	3220 KVA
15	Capacity of the feeder in Amps	NIL
16	Whether SRTPV installation is technically feasible, if the total SRTPV capacity is less than or equal to the 11kV feeder capacity	Yes/No (It is not possible to state reasons)

The Transformer shall be loaded upto 80% of capacity.  
Enclosure: 11kV feeder & LT Distribution sketch of the transformer.

I hereby certify that the above said SRTPV installation is technically feasible.

Signature and Name  
AEE(Ele)  
C, O&M Section  
BESCOM

**VISWAS. K**  
 Asst. Electric Engr., (Ele.)  
 Hongasandra O & M Unit  
 53, Sub-Division

Scanned by CamScanner

**Bengaluru, Karnataka, India**  
23, AMR Tech Park Internal Rd, Hongasandra, Bengaluru, Karnataka  
560068, India  
Lat 12.900996°  
Long 77.631057°  
31/12/21 03:36 PM

GPS Map Camera

**PRINCIPAL**  
 The Oxford College of Engineering  
 Bommanahalli, Hosur Road  
 Bengaluru-560 068